Public Class Form1

Dim temp As String

Private Sub Form1_Load(ByVal sender As System.Object, ByVal e As System.EventArgs) Handles MyBase.Load SerialPort1.Open()
Timer1.Enabled = False

End Sub

Private Sub Timer1_Tick(ByVal sender As System.Object, ByVal e As System.EventArgs) Handles Timer1.Tick SerialPort1.Write(temp)

End Sub

Private Sub Button1_MouseDown(ByVal sender As Object, ByVal e As System.Windows.Forms.MouseEventArgs) Handles Button1.MouseDown temp = "W"

Timer1.Enabled = True

End Sub

Private Sub Button1_MouseUp(ByVal sender As Object, ByVal e As System.Windows.Forms.MouseEventArgs) Handles Button1.MouseUp Timer1.Enabled = False

End Sub

 $Private Sub \ Button 2_Mouse Down (By Val \ sender \ As \ Object, By Val \ e \ As \ System. Windows. Forms. Mouse Event Args) \ Handles \ Button 2. Mouse Down \ temp = "D"$

Timer1.Enabled = True

End Sub

Private Sub Button2_MouseUp(ByVal sender As Object, ByVal e As System.Windows.Forms.MouseEventArgs) Handles Button2.MouseUp Timer1.Enabled = False

End Sub

Private Sub Button3_MouseDown(ByVal sender As Object, ByVal e As System.Windows.Forms.MouseEventArgs) Handles Button3.MouseDown temp = "S"

Timer1.Enabled = True

End Sub

Private Sub Button3_MouseUp(ByVal sender As Object, ByVal e As System.Windows.Forms.MouseEventArgs) Handles Button3.MouseUp Timer1.Enabled = False

End Sub

 $Private Sub \ Button 4_Mouse Down (By Val \ sender \ As \ Object, By Val \ e \ As \ System. Windows. Forms. Mouse Event Args) \ Handles \ Button 4. Mouse Down \ temp = "A"$

Timer1.Enabled = True

End Sub

End Sub

End Class